



powerFab, inc.

Scrubber Screens

Original screens were replaced annually. By changing material grade, changeout is every four years.



Chromium Carbide Liners



Original AR400F liners were replaced every two years. With change to chromium carbide, these liners have been in service for four years and showing no signs of wear.